Size of the Opening in the Pentagon on 9/11

Prepared for the August 31, 2016 9/11 and Other Deep State Crimes Teleconference

Wayne H. Coste, PE Truth Outreach, Inc.





Table of Contents

- "Jenga Block" Wall (with "Blast Resistant" Windows) Crumbles
- Overview of conflicting claims
- Composite photos
- South end of the first floor opening
- North end of the first floor opening
- Hanging remnant of column 16
- Addendum Hole in Second Floor Façade





Purpose of the Presentation

Illustrate the evidence supporting:

The Pentagon exterior wall had no reinforced concrete wall sections and had limited structural resistance to an 'event'

A continuous opening exists in the first floor of the Pentagon façade that is approximately 100 feet wide and extends from column 8 to column 18.

 No other aspect of the Pentagon 'event' is being discussed in this presentation





Size of the Opening in the Pentagon on 9/11

"JENGA BLOCK" WALL (WITH "BLAST RESISTANT" WINDOWS) CRUMBLES





What is Visible in the Post-Collapse Wall Photos

- All components of the wall are clearly visible in the post-collapse photos
 - Limestone exterior sheathing
 - Bricks
 - Support columns
 - Steel window frame supports
 - Blast resistant windows





"Jenga Block" Wall Crumbled Exposing All Wall Components



Limestone facing pieces

Brick under limestone

Steel window frame

"Blast-resistant" window

Limestone border pieces

Steel Supported Window Frames and "Jenga Block" Wall Parts

Blast-resistant windows

Steel window frames

Limestone border pieces

Shattered tree stump



Because there is important news the "free press" isn't telling you

911TruthOutreach.org

Steel Frames Support Windows Frames Are Not Building Structure



"Structural steel, running through all five floors, strengthens the walls around the blast resistant window units. A geo-technical mesh is stretched between the steel tubes to prevent debris from becoming shrapnel in the event of an external explosion."






"Blast-Resistant Windows" not "Blast-Resistant Walls"

"Under the renovation plan [...] the outer wall was reinforced with structural steel tubing to increase its lateral stability and provide support to new blast-resistant windows. The building's windows indeed required special attention. Analysis of attacks on large structures elsewhere bore out that flying glass from blast-shattered windows caused many casualties, including deaths. The Pentagon's original [...windows ...] offered no resistance to blast-generated fragmentation. Reinforcing the windows on the outside of the E Ring and the A Ring would diminish the blast and fragmentation effects of exterior explosions. New windows for the E Ring, the same size as their predecessors but with glass 1½ inches thick and weighing more than a ton apiece, were welded into special tubular steel frameworks. On 11 September many survived the blast."

Source: Pentagon 9/11, Defense Studies Series, Alfred Goldberg et al, Office of the Secretary of Defense, Washington, D.C., 2007

telling you





Video of Impacted Wall Crumbling (Poor Video Quality)

Bob Pugh "I heard a crunch and I looked back to my left and the Pentagon – actually the floors were collapsing right across from where I was standing." https://www.youtube.com/watch?v=-xtEJ4zrIPM at 9:20



Source: https://www.youtube.com/watch?v=bCspmm5YIXE at 25:50





Size of the Opening in the Pentagon on 9/11

CONFLICTING CLAIMS ABOUT SIZE OF OPENING IN FAÇADE





Because there is important news the "free press" isn't telling you

911TruthOutreach.org

9/11 and Other Deep State Crimes Teleconference August 31, 2016

Many Claim the Opening was Only 18 feet - Some Say 10 feet

Example image



telling you





This Photograph is Used to Support an 18 Foot Opening



18 foot opening in second floor wall frequently asserted to be the largest opening in the wall.

Opening in first floor is not visible due to firefighting spray.





This Photograph is Also Used to Support a 10 Foot Hole



Some claim the opening is only 10 feet because column 14AA is assumed intact on the second floor.

Opening in first floor is not visible due to firefighting spray.






Because there is important news the "free press" isn't telling you

Another Analysis Estimates the Façade Opening at 96 Feet

This analysis is focused on the opening in the first floor







Size of the Opening in the Pentagon on 9/11

COMPOSITE PHOTOS





Composite Photos

- Composite photos have been made of the Pentagon wall by several people
- The accusation, by some, is that they are "photo shopped"
 - A composite photo by definition is the merger of multiple images
 - "Photo shopped"
 - May be an accurate term
 - Neutral about the quality of the resulting information

Composite Photo Question

- The question is whether the composite
 - Accurately reflects the original information
 - Misrepresents the information in the original(s)



Composite Photo Assertion

- Key assertions behind the composite photos are:
 - A large opening exists in the first floor
 - The opening is up to 100 feet wide
 - The large opening is contiguous





Creation of a Composite

- Take existing photos
 - Cut
 - Trim
 - Adjust for perspective
 - Overlay
- Top image shows best view of the north end of the opening





Composite #1

North
end of the
opening
has no
clear fronton view
pictures
before the
total wall
collapse.







Composite #2

North
end of the
opening
has no
clear fronton view
pictures
before the
total wall
collapse.








Because there is important news the "free press" isn't telling you

911TruthOutreach.org

9/11 and Other Deep State Crimes Teleconference August 31, 2016

Best Evidence Supports an Opening of About 100 Feet

Opening in the façade between columns 8 and 18 is about 100 feet






Because there is important news the "free press" isn't telling you


911TruthOutreach.org

Post Fire Photo Showing Columns 9AA and Another ? (9A?)



ASCE Report Shows Row "AA" Columns and Row "A" Columns

9AA and 9A



ASCE: Figure 7-9 (Part)





Because there is important news the "free press" isn't telling you

911TruthOutreach.org

9/11 and Other Deep State
Crimes Teleconference
August 31, 2016

Size of the Opening in the Pentagon on 9/11

SOUTH END OF THE FIRST FLOOR OPENING





Because there is important news the "free press" isn't telling you

911TruthOutreach.org


South End of the Opening

- South end of the opening terminates at Column 18
- Columns 15 to 17 have remnants hanging
 - Claims have been made that
 - The columns are intact at the bottom
 - The columns rising from the floor are angled outward
 - Wrong angle for an external momentum event
 - Multiple views show that they are hanging





South End of Opening Minutes After the Event



Material burning is inside the Pentagon (not outside). The burning material is seen under the remnant of hanging Column 16 and to right of shattered tree stump.






Iconic Photo #1: Worth a Close Look








Opening in Façade Extends from Column 12 (at least) to 18







Façade Opening Extends from Col 18 to (at least) Col 12




August 31, 2016


Façade Opening Extends from Col 18 to (at least) Col 12



Iconic Photo #2



Fires Extinguished on Outside; Façade Doesn't Hide Interior Fires







Size of the Opening in the Pentagon on 9/11

NORTH END OF THE FIRST FLOOR OPENING






Because there is important news the "free press" isn't telling you

911TruthOutreach.org


Opening in the Façade from Columns 8 to 13







Exterior Façade Between Columns 8 and 13 is Absent







Post Collapse View Shows North End of Opening

Photo Taken Approximately Perpendicular to Column 14







Close-up of North End of Opening







Other Views of the North End Showing Columns 9AA and "?"



Window Frame Support







Because there is important news the "free press" isn't telling you

911TruthOutreach.org

Column 9AA and Nothing to its Right





ASCE Pentagon Building Performance Report





Because there is important news the "free press" isn't telling you

911TruthOutreach.org

Size of the Opening in the Pentagon on 9/11

HANGING REMNANT OF COLUMN 16






Because there is important news the "free press" isn't telling you

911TruthOutreach.org

Remnants of Col. 15, 16 and 17 Hanging from Second Floor




telling you





Remnants of Columns 15 - 17 Hanging From Structure

Columns 15-17 pushed in direction of impact and hanging from second floor. These are not columns 14-16 rising from the foundation (wrong intersection)







Pre-Collapse Image #1 (from right)



Column 16 Hanging





Pre-Collapse Image #2 (to left)




Column 16 Hanging





Remnant of Column 16 Shown Bent Inwards Hanging From Top




Source: https://www.youtube.com/watch?v=bCspmm5YIXE at 13:32





Because there is important news the "free press" isn't telling you

Remnant of Column 16 Shown Bent Inwards Hanging From Top



Source: https://www.youtube.com/watch?v=bCspmm5YIXE at 12:12





Because there is important news the "free press" isn't telling you

Another View of Column 16 Hanging from the Second Floor 9/11 First Two Handheld Camera Videos Of Pentagon After Explosion




Source: https://www.youtube.com/watch?v=bCspmm5YIXE at 16:39





Because there is important news the "free press" isn't telling you

Col.16 Hanging from Second Floor View from Left and Right



View from left

View from center right

View from right






Because there is important news the "free press" isn't telling you

911TruthOutreach.org

Columns Are Clearly *Hanging* by Rebar from the Top

Because of questions about whether column 16 continues to the floor, the lower object was scrutinized and shown to be a stump of a tree in front of column 16







Because there is important news the "free press" isn't telling you

911TruthOutreach.org

Zoom-In of Post Collapse Image Showing Tree Stump

Photo taken looking north and east







Zoom-In of Post Collapse Image Showing Tree Stump

Photo taken looking directly east

Splintered Tree Stump







Size of the Opening in the Pentagon on 9/11

ADDENDUM I – HOLE IN SECOND FLOOR FAÇADE





Because there is important news the "free press" isn't telling you

911TruthOutreach.org

Opening in Second Floor Appears Like Sheet of Wall Fell

Clean break at the top and along sides suggest that the façade may have fractured and fallen away. Photos of debris removal could provide insights.









Size of the Opening in the Pentagon on 9/11

ADDENDUM II – EXAMPLE OF "HOLE TOO SMALL" MATERIALS





Because there is important news the "free press" isn't telling you

911TruthOutreach.org

"Hole Too Small" Error is Widespread

- Many pentagon commenters
 - Ignore the 100 foot opening in the first floor
 - Erroneously state the hole is "too small"
- "Exit Hole" claimed to be "Entrance Hole"
 - A popular YouTube video with nearly 5 million views claims: "C" Ring exit hole with entrance
 - Conspiracy Card
 - I remember receiving / picking up this card (or a similar one) a long time ago





9/11 Loose Change Final Cut

"The Pentagon's outer wall has a hole approximately 20 feet in diameter on the first and second floor -- and visible damage 90 feet across the first floor."







ZERO: An Investigation into 9/11

"According to the official story, The American Airlines Boeing 757 disappeared inside this hole. Can you see it? 5 meters, I repeat 5 meters in diameter."



telling you





Major General Albert N Stubblebine III

"I look at the hole in the Pentagon -- and I look at the size of an airplane that was supposed to have hit the Pentagon. The plane does not fit in that hole."








Thierry Meyssan

" ... it can be seen that only the nose of the Boeing enters the building ... No trace of impact is visible outside that of the nose of the Boeing."








Popular Video Confuses C-Ring Exit Hole With Impact Site

This video does not mention – or show – any of the damage to the first floor facade



Source: https://youtu.be/yRPWLqc5T20 at 1:36





Because there is important news the "free press" isn't telling you

Popular Pentagon "Truth" Card Misrepresents the Impact Site

How could a Boeing 757 penetrate the reinforced outer walls of the Pentagon...leave a small entry hole and vanish with no substantial debris?



telling you





Because there is important 911 TruthOutreach.org news the "free press" isn't 9/11 and Other Deep State

Questions



