The Tree At Column 16: What it Tells Us About the Event at the Pentagon

Prepared for the April 26, 2017 9/11 Truth and Other Deep State Crimes Teleconference

Wayne H. Coste, PE Truth Outreach, Inc.





April 26, 2017

Table of Contents

- Overview of the tree at Column 16
- Probable sequence for tree impact and movement
- Tree branches seen along north side of impact area
- The tree trunk between Columns 5 and 8
- Tree debris on the Pentagon lawn
- Questions





Why the Tree at Column 16 Matters to the Pentagon Discussion

OVER VIEW OF THE TREE AT COLUMN 16





Tree at Column 16


- Tree at column 16 is large identifiable object
 - Movement of a large identifiable object is subject to the laws of physics
 - Trunk is severed
 - A shattered tree stump remains
 - Tree branches seen to the north of impact area
 - Photographs taken after the event
 - Document the presence of the lower tree trunk
 - Lower tree trunk thrown over 100 feet northward
 - Supports the large plane impact scenario






Importance of Tree at Column 16

- Displacement of the tree above the stump:
 - Movement can't be explained by other theories
 - Unexplainable by a "cruise missile" into the building
 - Unexplainable by an exploding drone or other plane
 - Unexplainable by dropped "bombs"
 - Unexplainable by North-of-Citgo flight path (wrong angle to knock lower tree trunk 100 feet north-ward)
 - Indicates a large momentum force from south
 - Supportive of the large aircraft reported by most witnesses as approaching / impacting



Before 9/11, a Large Tree is Seen Slightly to the Left of Column 16







West Wall of the Pentagon Before 9/11








Because there is important news the "free press" isn't telling you

911TruthOutreach.org

9/11 Truth and Other Deep State Crimes Teleconference April 26, 2017

After the 9/11 Event Tree Vanishes Without Comment

In reviewing years of discussions about the Pentagon, only once was a stump of a tree at Column 16 mentioned – with no follow-up about where the tree went.







Plane approaches the tree at Column 16.







Plane begins to knock the tree forward.







Tree fades away in the video – and from any discussion.







Tree at Column 16 is again written out of the Pentagon's 9/11 history.








While the Stump Remains Visible; It is Ignored

The stump of a tree in front of column 16 is often claimed to be the lower part of the severed column 16 – due to 'perspective' associated with telephoto lenses.







Because there is important news the "free press" isn't telling you

911TruthOutreach.org

9/11 Truth and Other Deep State Crimes Teleconference 13 April 26, 2017

Zoom-In of a Post Collapse Image Showing Tree Stump


Photo taken looking north and east








Shattered Tree Stump Visible in Post Collapse Photos



Zoomed in








Why the Tree at Column 16 Matters to the Pentagon Discussion

PROBABLE SEQUENCE FOR TREE IMPACT AND MOVEMENT





Plane impacts tree at column 16 from south-west side. Leading main wing spar between engine and fuselage is the most likely impacting mass.








Stump is immovable and remains embedded in the ground.


Lower part of impacted trunk is knocked / accelerated northward.








Northward momentum moves entire tree north







Severed tree lands in area between columns 5 and 8







Why the Tree at Column 16 Matters to the Pentagon Discussion

TREE BRANCHES SEEN ALONG NORTH SIDE OF IMPACT AREA






Tree Branches Seen Along North Side of Impact Area

- Tree branches seen at the north end of the impact area
 - Overlooked by 9/11 Pentagon analysts
 - Presence has been unexplained
 - Where did they come from?
 - How did they get there?
 - Some hypothesized that they were rebar from columns that were exploded outward





In "Smoke Curtain," Tree Branches are Claimed to be Outwardly Bowed Columns



Source: https://www.youtube.com/watch?v=4fvJ8nFa5Qk at 0:59:16






State Crimes Teleconference 23

April 26, 2017


View of North Side of Impact Area With Columns Numbered








Close-up of Tree Branches
































Why the Tree at Column 16 Matters to the Pentagon Discussion

THE TREE TRUNK BETWEEN COLUMNS 5 AND 8





Tree Trunk Visible During Firefighting Period








Close-up Shows Section of Tree Trunk with Branches







Base of Tree (Formerly in front of Column16) Limbed on Afternoon of 9/11



Source: By PH2 JIM WATSON, USN -

http://www.defenseimagery.mil/imageRetrieve.action?guid=abcf9bf8149943e4e89f0a80a96930b828fb83 9d&t=2, Public Domain, https://commons.wikimedia.org/w/index.php?curid=25426471





Zoom-In of Limbed Tree Trunk (Photo 1)







Zoom-In of Limbed Tree Trunk (Photo 2)







Why the Tree at Column 16 Matters to the Pentagon Discussion

TREE DEBRIS ON THE PENTAGON LAWN





Tree Branches Among the Debris

Pentagon lawn is littered with tree debris consistent with the tree at Column 16. Alleged deceptive staging of debris -- including large and small tree branches -- would be unexpected.







Tree Branches in Background of Large Piece of Debris



Photo: Mark Faram





April 26, 2017

Littered Debris Includes Vegetation Consistent with Column 16 Tree







Two Surviving Trees Near the Heliport Firehouse







Satellite Photograph on Sept 7 Shows the Tree at Column 16

Tree at column 16 was present on Sept 7. Stump was shattered – not cut with a chainsaw.





Source: https://web.archive.org/web/20050212002810/http://www.spaceimaging.com/gallery/9-11/Pentagon/Pentagon_9_7_01.jpg





Snapped Branch of Nearby Tree Remains Hanging

Tree trunk identified in slide 31 did not snap from the tree at the point circled below







Because there is important news the "free press" isn't telling you

911TruthOutreach.org
9/11 Truth and Other Deep

State Crimes Teleconference⁴²
April 26, 2017

Questions



